

Heat one note:

During this heat, the chief of sound set up the meter incorrectly and resulted in readings 3 to 5 or more dBA higher than actual. Please disregard if you were given a sound warning in the 1<sup>st</sup> heat.

However, the meter was working correctly during 3<sup>rd</sup> heat. If you see a reading over 97.0 dBA during the heat, you are very close to the limit, and could well exceed it when atmospheric conditions align against you.

Steve Wynveen

Chief of Sound